

**Presentation to ANSAC** 

Bob Mussetter, Ph.D., P.E.

# **Definition of Navigability**

# A.R.S. § 37-1101(5)


"Navigable" or "navigable watercourse" means a watercourse that was in existence on February 14, 1912, and at that time was used or was susceptible to being used, in it ordinary and natural condition, as a highway for commerce, over which trade and travel were or could have been conducted in customary modes of trade and travel on water.

# **Definition of Navigability**

#### PPL Montana


• ...evidence [of present-day, primarily recreational use] must be confined to that which shows the river could sustain the kinds of commercial use that, as a realistic matter, might have occurred at the time of statehood.

#### **Channel Classification Relevant to Gila River Navigability**














# **Channel Pattern IS Relevant to Navigability**

#### Braided channels:

- Wide, shallow cross section
- Multiple, unstable (i.e., shifting) channels
- NOT conducive to boating



# **Channel Pattern IS Relevant to Navigability**

United States v Utah (283 U.S. 85)

The principal impediment to navigation is (*sic*) found is shifting sandbars....

# **Gila River Dynamics**

# Mid-1800s:


 Gila River may have been single-thread channel during periods of extended low flow; however...


# Strongly flood driven:

Periods of increased flood frequency are more likely to be associated with wide, braided channel conditions on the Gila River (Burkham, 1972; Huckleberry, 1993b). Huckleberry (1996), p 4


The channel changed its geometry when the sustained flow of the floods of January, 1993 converted the compound channel above Pima Butte into a single, wide, braided channel. Huckleberry (1996), p 8

#### **Gila River at Kelvin Flows**







# **Annual Flood Peaks: Snowmelt and Monsoon**




#### Similar Variability in Annual Volume Pre- and Post-statehood



# Annual peak is correlated with annual volume




# Flood-induced Changes in Channel Width




# Location of GLO Plat (April 24, 2013)




# Flood-induced Changes in Channel Width




# Location of GLO Plat (March 7, 2014)




# Flood-induced Changes in Channel Width




# Location of GLO Plat (March 7, 2014)



#### Historical Changes in Gila River (Pima to San Carlos Res )



# Channel Width Change, Middle Gila River



# **Summary of Opinions**

# Mid-1800s:

- Portions of Gila River had single-thread channel lined with thick stands of woody riparian vegetation.
- It may have been possible to float a small boat in some reaches under some flow conditions

## ■ <u>1895 to1916</u>:

- Large floods scoured vegetation, eroded the banks, widened the channel,
- Gila River developed wide braided planform.

# **Summary of Opinions**

- Early-1900s, including date of statehood:
  - Extensive reaches were dry; carried little or no flow except during flooding.
  - Braided planform and low to non-existent flows would have made commercial navigation impractical.
  - During flood periods, navigation also impractical due to hazardous conditions, debris, uncertain and unstable channels.
- Prior to mid-1800s:
  - Reconstructed flow records show mid-1800s unusually dry
  - Large floods routinely occurred in the ordinary and natural condition of the Gila River

# **Summary of Opinions**

The Gila River was NOT used nor susceptible to being used, in it ordinary and natural condition, as a highway for commerce, using customary modes of trade and travel on water at the time of Arizona's statehood.